



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

May 28, 2008

Reviewed SW

<b>Mine Name:</b> Solar Wind	<b>Permit Number:</b> S0230061
<b>Operator Name:</b> Utah Minerals and Fossil Inc.	<b>Inspection Date:</b> 05-14-08
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 4:00 pm
<b>Other Participants:</b> None	<b>Mine Status:</b> APP

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** None listed **Bond Amount:** \$ 5,365. No permit fee has been received

**Purpose of Inspection:** Routine annual Inspection.

**Inspection Summary:** This site consists of a small disturbance, probably less than a couple of acres in size, including the road. No new improvement to the access road. Mine site with dump was 0.4 acres of disturbance. Previous Inspection noted that a backhoe was on site; the backhoe has been removed.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** DOGM to continue annual inspections and monitor the site when in the area. Permit fee is delinquent, operator has 30 days to update; Mining will be suspended until resolved.

**Inspector's Signature** L. Heppler

LAH:pb

cc: John Holfert, Operator

Sheri Wysong, BLM, Fillmore FO

Attach - GIS

O:\M023-Juab\S0230061-SolarWind\inspections\Insp\_SolarWind\_05-14-08.doc

Inspection Date: May 14, 2008  
Page 2 of 2  
M/023/0061

Photos Taken 05-14-08

